


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-041	Smoke	9/5/2008	ADS/TM	S15GG1015MH	Dry	Yes	1,609.80



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-041	Smoke	9/5/2008	ADS/TM	S15GG1015MH	Dry	Yes	1,609.80

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S15GG1019G1	S15GG1019MH	S15GG1014MH	349.9973	8
S15GG1018G1	S15GG1018MH	S15GG1014MH	147.1403	8
S15GG1029G1	S15GG1029MH	S15GG1004MH	116.9874	8
S15GG1024G1	S15GG1024MH	S15GG1018MH	262.1804	8
S15GG1004G1	S15GG1004MH	S15GG1019MH	4.345363	8
S15GG1014G1	S15GG1014MH	S15GG1015MH	313.9693	8
S15GG1035G1	S15GG1035DE	S15GG1018MH	96.17275	8
S15GG1015G1	S15GG1015MH	S13GG1001MH	319.0034	8

Observations & Photos

Obs_ID S1028-041-OB01

Address 2653 Loyola Southway


Status Private

Source Cleanout

Location Yard - back

Nearest MH S13GG1001MH

Comments Smoke from cleanout in back yard. 2653 Loyola Southway



Picture \S1028-041-OB01-P01.jpg

Comments Back of house, 2653 Loyola Southway

Obs_ID S1028-041-OB02

Address 2502 Oswego Ave

Status Private

Source Cleanout

Location Yard - back

Nearest MH S15GG1029MH

Comments Smoke from cleanout in back yard. 2502 Oswego Ave



Picture \S1028-041-OB02-P01.jpg

Comments Back of house, 2502 Oswego Ave

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-041	Smoke	9/5/2008	ADS/TM	S15GG1015MH	Dry	Yes	1,609.80

Obs_ID S1028-041-OB03

Address 2504 Oswego Ave

Status Private

Source Cleanout

Location Yard - back

Nearest MH S15GG1029MH

Comments Smoke from cleanout in back yard. 2504 Oswego Ave



Picture \S1028-041-OB03-P01.jpg

Comments Back of house, 2504 Oswego Ave
